

Inspection Photos  
Operator: Simcoe  
API: 067-07960  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with crested wheatgrass, intermediate wheatgrass, and smooth brome. Sparse vegetation on the southern fill slope needs to be assessed during the 2022 growing season and determine whether spot seeding is needed.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of developed neighborhood infrastructure. Park space is present south of project area.