

Final Reclamation Inspection

December 21, 2021

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 478843

Inspection Document #: 697503585

Weld County, CO

NENE Section 30 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Facility 9
Location ID: 478843



Photo 1. 2019 COGCC GISOnline aerial imagery illustrates the KPK Facility 9 Flowline System (red line).



Inspection Photos
Location Name: Facility 9
Location ID: 478843



Photo 2. Photo taken from the previous tank battery location, facing East. Photo illustrates unused KPK equipment related to their flowline system at the approximate location 40.114877, -104.81312.

