

Inspection Photos
Location Name: Antelope F-18
Location ID: 429686



Photo 1 – Wellheads – Unused Rods and Wellhead Parts



Photo 2 – Wellhead – Unused Rods and Wellhead Parts

Inspection Photos
Location Name: Antelope F-18
Location ID: 429686



Photo 3 – Separators



Photo 4 – Tank Battery

Inspection Photos
Location Name: Antelope F-18
Location ID: 429686



Photo 5 – Tank Battery Signs



Photo 6 – Tank Battery Sign



Inspection Photos
Location Name: Antelope F-18
Location ID: 429686



Colorado Oil and Gas Conservation Commission
40.40523, -104.37018, 4559.8ft, 67°
12/15/2021 13:46:02

Photo 7 – ECDs