

Inspection Photos
Location Name: Antelope I-18 PAD
Location ID: 418173



Photo 1 – Wellheads

Photo 2 – Unmarked Risers at Wellheads

Inspection Photos
Location Name: Antelope I-18 PAD
Location ID: 418173



Photo 3 – Unmarked Riser at Compressor

Photo 4 – Compressor

Inspection Photos
Location Name: Antelope I-18 PAD
Location ID: 418173



Photo 5 – Separators

Photo 6 – Separators

Inspection Photos
Location Name: Antelope I-18 PAD
Location ID: 418173



Colorado Oil and Gas Conservation Commission
40.39565, -104.35972, 4569.1ft, 244°
12/15/2021 14:12:05



Colorado Oil and Gas Conservation Commission
40.39561, -104.35972, 4562.0ft, 246°
12/15/2021 14:11:54

Photo 7 – Tank Battery Signs

Photo 8 – Tank Battery

