

**Inspection Photos**  
**Location Name: Antelope 31-34-3HNB**  
**Location ID: 431023**



**Photo 1 – Risers have been marked**



**Photo 2 – Risers have been marked**

**Inspection Photos**  
**Location Name: Antelope 31-34-3HNB**  
**Location ID: 431023**



**Photo 3 – Separators**



**Photo 4 – Tank Battery**





**Inspection Photos**  
**Location Name: Antelope 31-34-3HNB**  
**Location ID: 431023**



**Photo 5 – Tank Battery Sign**



**Photo 6 – ECDs**



**Inspection Photos**  
**Location Name: Antelope 31-34-3HNB**  
**Location ID: 431023**



**Photo 7 – Pumping Unit**




**Photo 8 – Wellhead**





**Inspection Photos**  
**Location Name: Antelope 31-34-3HNB**  
**Location ID: 431023**



**Photo 9 – Unmarked Riser at Wellhead**