

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 1 – Signs at Entrance



Photo 2 – Gas Meter Shed

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 3 – Compressor




Photo 4 – Tank missing Labels

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415




Photo 5 – Unmarked Riser at Compressor



Photo 6 – Separators and ECDs

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 7 – Risers have been marked



Photo 8 – Tank Battery



Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 9 – Tank Battery Signs



Photo 10 – Wellheads



Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 11 – Stained Soil at Wellheads



Photo 12 – Stained Soil at Wellheads

Inspection Photos
Location Name: State Antelope J-12 PAD
Location ID: 431415



Photo 13 – Stained Soil at Wellheads



Photo 14 – Gas Meter Injection House

