

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402910429

Date Received:

12/28/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Mike Storey

Phone

970-939-6353

Email

Mstorey@CiviResources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696303846

Inspection Date: 12/14/2021

FIR Submit Date: 12/14/2021

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 429990

Location Name: Antelope Number: F-31 PAD County: _____

Qtrqtr: NWN Sec: 31 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.362190 Longitude: -104.370700

FACILITY - API Number: 05-123-00 Facility ID: 429990

Facility Name: Antelope Number: F-31 PAD

Qtrqtr: NWN Sec: 31 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.362190 Longitude: -104.370700

CORRECTIVE ACTIONS:

1 CA# 158687

Corrective Action: Comply with Rule 606

Date: 12/17/2021

Response: CA COMPLETED

Date of Completion: 12/28/2021

Operator Comment: Risers have been marked in compliance with Rule 606.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed: _____

Title: Regulatory Analyst

Date: 12/28/2021 11:16:46 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|-------------------|
| 402910433 | Inspection Photos |
|-----------|-------------------|

Total Attach: 1 Files