

Inspection Photos

API: 071-06814

Operator: WAPITI OPERATING LLC

Inspection Date: 12/27/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06814 | Date: 12/27/2021

Inspection Photos



Photo 1. Facing southeast along the road. Areas of erosion along the road side have been filled in and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06814 | Date: 12/27/2021

Inspection Photos



Photo 2. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06814 | Date: 12/27/2021