

Inspection Photos

API: 071-09514

Operator: WAPITI OPERATING LLC

Inspection Date: 12/27/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09514 | Date: 12/27/2021

Inspection Photos



Photo 1. Facing southeast along the road. Areas of erosion along the road side have been filled in and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 12/27/2021

Inspection Photos



Photo 2. Facing southeast along the road. Areas of erosion along the road side have been filled in with rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 12/27/2021

Inspection Photos



Photo 3. The culverts along the road have been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 12/27/2021

Inspection Photos



Photo 4. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 12/27/2021

Inspection Photos



Photo 5. There is a dripping water leak at the wellheads that needs to be fixed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09514 | Date: 12/27/2021