

# Inspection Photos

API: 071-06816

Operator: WAPITI OPERATING LLC

Inspection Date: 12/27/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06816 | Date: 12/27/2021

## Inspection Photos



**Photo 1.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06816 | Date: 12/27/2021

## Inspection Photos



**Photo 2.** There is a dripping water leak at the wellheads that needs to be fixed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06816 | Date: 12/27/2021