

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33SWNE

Location ID: 335143



Photo #5499 from entrance to location.




Photo #5500 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /33SWNE

Location ID: 335143




Photo #5501 Storage tank not labeled.



Photo #5502 Sight glass indicates the storage tank is full of an unknown fluid.