

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NENW

Location ID: 335287



Photo #5503 from entrance to location.



Photo #5504 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /33NENW

Location ID: 335287



Photo #5505 Storage tanks not labeled.



Photo #5506 Sight glass indicates that the storage tank is full of an unknown fluid.