

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESW

Location ID: 335406



Photo #5507 from entrance to location.



Photo #5508 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESW

Location ID: 335406



Photo #5509 Storage tanks not labeled.



Photo #5510 Sight glass indicates the storage tank is full of an unknown fluid.