


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWNW

Location ID: 335129



Network: Dec 27, 2021 at 1:02:37 PM MS
Local: Dec 27, 2021 at 1:02:37 PM MS
+39.496114, -108.00855



Network: Dec 27, 2021 at 1:02:40 PM MS
Local: Dec 27, 2021 at 1:02:40 PM MS
+39.496114, -108.00855

Photo #5511 from entrance to location.

Photo #5512 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWNW

Location ID: 335129




Photo #5513 Multiple wellheads signs weathered and not legible.




Photo #5514 Multiple wellheads sign weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWNW

Location ID: 335129



Photo #5515 Storage tank not legible.



Photo #5516 Sight glass indicates the storage tank is full of an unknown fluid.