

# Inspection Photos

API: 071-09301

Operator: OGRIS OPERATING LLC

Inspection Date: 12/27/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09301 | Date: 12/27/2021

## Inspection Photos



**Photo 1.** Facing southwest along the main road. The road has been graded and additional road base was added.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09301 | Date: 12/27/2021

## Inspection Photos



**Photo 2.** The side of the main road and stream bank has been resloped and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09301 | Date: 12/27/2021

## Inspection Photos



**Photo 3.** The area of erosion further along the road has been repaired and a culvert has been installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09301 | Date: 12/27/2021

## Inspection Photos



**Photo 4.** The side of the main road and stream bank has been resloped and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09301 | Date: 12/27/2021

## Inspection Photos



**Photo 5.** The cattle guard along the road has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09301 | Date: 12/27/2021