

Inspection Photos

Operator: Kinder Morgan
API: 083-06454
Date: 12/21/2021



Photo 1. View of the project are from the well entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation appears to be progressing similar to reference area with grasses such as crested wheatgrass, smooth brome, and western wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Location partially snow covered.



Photo 4. View of the reference area comprised of grass field with smooth brome and crested wheatgrass.