

Inspection Photos  
Operator: Kinder Morgan  
API: 083-06584  
Date: 12/21/2021



Photo 1. View of the project are from the well entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, crested wheatgrass, sagebrush, and cliffrose.





Photo 3. View of the western project area from the southwestern corner facing northward.





Photo 4. View of the reference area comprised of pinyon and juniper woodland with sagebrush, palmer's penstemon, rock goldentrod, and cat's eye.