

Inspection Photos

Operator: Kinder Morgan
API: 083-06374
Date: 12/21/2021



Photo 1. View of the project are from the well entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with Indian ricegrass, crested wheatgrass, sagebrush, and rubber rabbitbrush.



Photo 3. View of the western project area from the southeastern corner facing northward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with sagebrush, James galleta, purple threeawn, Indian ricegrass, palmer's penstemon, rock goldentrod, and cat's eye.