



00250519



WELL SITE INSPECTION FORM

Well Name #2 Du Bois API Number 05 - 075 6598-1 J
 Operator Lewis + Clark Permit # _____
 Location NE NW 7-9N-52W County Logan
 Field Prabuni Inspector EBB

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) _____ Fail(N) _____ Date _____ ND _____ DG _____ WO _____ PR _____ SI _____ TA X

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES _____ NO _____ Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
 Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
 Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
 Equipment _____ Meter Run: Yes _____ No _____
 Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
 Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____
 Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____
 Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection 11-21-94

Comments: Well head disconnected. No Equipment
Tank battery at this site. 4-300, VHTO, Cmt. Skim
2 pits 200x200,
Install fence around battery + pits
Install Berm around tanks
Install sign

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____