

Final Reclamation Inspection

December 21, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 445916

Inspection Document #: 697503592

Weld County, CO

NWSW Section 31 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 445916



Photo 1. Photo taken from the remediation project, facing West. Photo illustrates Operator has managed weeds.

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 445916



Photo 2. Photo taken from the remediation project, facing Northwest. See comments under Photo 1.