

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32NESW

Location ID: 335325




Photo #5528 from entrance to location.



Photo #5529 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32NESW

Location ID: 335325



Photo #5530 Storage tanks not labeled.



Photo #5531 Sight glass indicates the storage tank is full of an unknown fluid.