

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSW

Location ID: 334918



Photo #5534 from entrance to location.




Photo #5536 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSW

Location ID: 334918



Photo #5537 Storage tanks not labeled.



Photo #5538 Sight glass indicates the storage tank is full of an unknown fluid.