

**Inspection Photos**  
**Operator: Kinder Morgan**  
**API: 083-06456**  
**Date: 12/21/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with Indian rickerass, crested wheatgrass, fourwing saltbush, western wheatgrass, blue grama, and rubber rabbitbrush. Location largely snow covered.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with sagebrush, James galleta, purple threeawn, Indian ricegrass, palmer's penstemon, rock goldentrod, and cat's eye.