

**Inspection Photos**  
**Location Name: Razor 25P**  
**Location ID: 444471, Spill ID 480257,480867**



**Photo 1 Flowline release excavation looking west**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Razor 25P**  
**Location ID: 444471, Spill ID 480257,480867**



COGCC  
40.80385, -103.80555, 4681.1ft  
12/22/2021 12:23:36

**Photo 2 Stockpiled waste on Razor 25P location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Razor 25P**  
**Location ID: 444471, Spill ID 480257,480867**



**Photo 3 Impact to surface east of Razor 25P location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Razor 25P**  
**Location ID: 444471, Spill ID 480257,480867**



COGCC  
40.80403, -103.80493, 4696.7ft  
12/22/2021 12:25:12

**Photo 4 Impacts to surface east of Razor 25P location and new entrance to Razor 25P location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Razor 25P**  
**Location ID: 444471, Spill ID 480257,480867**



COGCC  
40.80434, -103.8049, 4690.5ft  
12/22/2021 12:25:44

**Photo 5 Impacts to surface east of Razor 25P location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources