

**Inspection Photos**  
**Location Name: Razor 250**  
**Location ID: 444465, Spill ID 479109**



**Photo 1 Material stored on Razor 250 location**



**Inspection Photos**  
**Location Name: Razor 250**  
**Location ID: 444465, Spill ID 479109**



**Photo 2 Flowline release excavation looking southeast**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Razor 250**  
**Location ID: 444465, Spill ID 479109**



**Photo 3 Second excavation to facilitate flowline repair**