

# Interim Reclamation and Stormwater Inspection

December 21, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 331598

Inspection Document #: 697503594

Weld County, CO

NESW Section 13 T2N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GUEST /3N-12HZ  
Location ID: 331598



**Photo 1.** Photo taken from the southern interim reclamation area of the well location, facing West. Photo illustrates interim reclamation areas have been grazed. Interim reclamation areas appear to have a higher abundance of cheatgrass than the previous inspection.



**Photo 2.** Photo taken from the southern interim reclamation area of the well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: GUEST /3N-12HZ  
Location ID: 331598



**Photo 3.** Photo taken from the southern interim reclamation area of the well location, facing East. See comments under Photo 1.



**Photo 4.** Photo taken from a portion of the interim reclamation area. Photo illustrates desirable vegetation that has been grazed.



Inspection Photos  
Location Name: GUEST /3N-12HZ  
Location ID: 331598



**Photo 5.** Photo taken from the southern interim reclamation area of the well location, facing West. See comments under Photo 6.



**Photo 6.** Photo taken from a portion of the interim reclamation area. Photo illustrates a List C Colorado noxious weed, puncture vine.

