

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/22/2021

Submitted Date:

12/30/2021

Document Number:

693700909**FIELD INSPECTION FORM**Loc ID 444472 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 LINCOLN STREET SUITE 4700City: DENVER State: CO Zip: 80290**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Wheeler, Steven		steven.wheeler@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479246	SPILL OR RELEASE	CL	07/19/2021		-	Razor 25N	EI

General Comment:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles			
Comment:	Unknown material pile is present on location- unknown whether pile is clean backfill or E&P Waste impacted material			
Corrective Action:	Operator shall identify material pile and either dispose or properly remove from location. Operator to provide documentation of ultimate disposal of sotckpiled material			Date: 02/28/2022

Spill/Remediation:

Comment:	COGCC has approved the closure/resolution of both Spill ID 479246 and Remediation Project 17626 for the Razor 25N location flowline release. Operator has not backfilled original excavation at flowlines.			
Corrective Action:	Operator to provide COGCC Engineering Integrity Group with root cause analysis for flowline failure. Operator to remove waste storage area and backfill excavations. Submit FIRR with disposal documentation and backfill photo documentation.			Date: 02/28/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700910	Razor 25N Photos 12-22-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621445