

Inspection Photos

API: 071-08481

Operator: OGRIS OPERATING LLC

Inspection Date: 12/29/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 12/29/2021

Inspection Photos




Photo 1. Facing east along the access road. The road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 12/29/2021

Inspection Photos



Photo 2. Facing northwest along the access road. The road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 12/29/2021

Inspection Photos



Photo 3. Facing east toward the well site..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08481 | Date: 12/29/2021