

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TBI PRODUCTION-67S96W /25SESW

Location ID: 324002



Photo #5545 from entrance to location.



Photo #5546 No battery sign located at the tank battery.