

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOLVAY-67S96W /2NWSW

Location ID: 334726



Photo #5557 from entrance to location.



Photo #5561 Storage tank not labeled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SOLVAY-67S96W /2NWSW

Location ID: 334726



Photo #5562 Sight glass indicates the storage tank is full of an unknown fluid.