

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SWNW

Location ID: 323936



Photo #5563 from entrance to location.



Photo #5564 Storage tanks not labeled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SWNW

Location ID: 323936



Photo #5565 Sight glass indicates the storage tank is full of an unknown fluid.