

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NENW

Location ID: 334903



Photo #5573 from entrance to location.



Photo #5574 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NENW

Location ID: 334903



Photo #5575 Storage tank not labeled.



Photo #5576 Sight glass indicates the storage tank is full of an unknown fluid.