

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/10/2021

Submitted Date:

01/05/2022

Document Number:

692200582

**FIELD INSPECTION FORM**Loc ID 378515 Inspector Name: Chollett, Shannon On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 99999

Name of Operator: OLD OPERATORS - STATUS UNKNOWN

Address: SEE COMMENT LINE IN WELL

City: XXXXXXXX State: XX Zip: \_\_\_\_\_

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Conklin, Curtis		curtis.conklin@state.co.us	
Duran, Alicia		alicia.duran@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205061	WELL	DA	02/24/1951	DA	007-05170	SHAHAN (OWP) 2	PA

**General Comment:**

This is an account of the OWP P&amp;A of this well.

**Inspected Facilities**Facility ID: 205061 Type: WELL API Number: 007-05170 Status: DA Insp. Status: PA**Workover**Comment:

November 1, 2021 Monday  
Arrived on location with equipment.

November 2, 2021 Tuesday  
Picked up Forklift in Durango and Mini X in Pagosa Springs and hauled to location.  
RMWS on location around 1 pm. Cut off top of casing, set work skid over the well.  
PU and RIH with 2-3/8" tbg Tagged at 242'. Land at 242' and broke circulation with  
water, Mixer pump. Circulated in 30 bbls and sucked up returns with Vac truck, black  
nasty water in returns until fresh water circulated. Water had entrained H2S 10 ppm  
which disappeared after bottoms up. Laid down tbg sdfn.

November 3, 2021 Wednesday/  
RU wireline. Pulled CBL from tag at 185' to surface. Casing shoe at 43'. RIH with tbg  
to 191'. Hook up to circulate, had to pick up 6' to break circulation. Mixed and pumped  
100 sks type 2 to fill well with approximately 1 bbl cement returns. POOH with tbg, RD  
equipment and moved off well.

November 9, 2021 Tuesday  
MI Mini -X and loader. Dug up and loaded 8 cu yds of top soil with night crawlers from  
well and hauled to disposal. Cut off casing and installed marker plate

November 10, 2021 Wednesday  
Caught soil sample from bottom of cellar. Hauled in 8 cu yds of clean top soil and filled  
cellar.

Corrective Action:

Date: