

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /21SWSW

Location ID: 323869



Photo #5588 from entrance to location.



Photo #5589 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /21SWSW

Location ID: 323869



Photo #5592 Storage tank not labeled.



Photo #5593 Sight glass indicates the storage tank is full of an unknown fluid.