

Inspection Photos  
Operator: Arkoma  
API: 067-05482  
Date: 12/22/2021



Photo 1. View of the southern project area from the southwestern corner facing center. Revegetation is progressing with western wheatgrass, smooth brome, and intermediate wheatgrass. Revegetation at final reclamation needs to be representative of the surrounding reference area.



Photo 2. View of the western fill slope from the southwestern corner facing northward.



Photo 3. View of the southern fill slope from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of open grass field with western wheatgrass, smooth brome, and crested wheatgrass.