

Inspection Photos  
Operator: Arkoma  
API: 067-05439  
Date: 12/22/2021



Photo 1. View of project area from the well pad entrance facing northward from the well pad entrance.



Photo 2. View of the central revegetation area from the southeastern corner facing northwestward. Revegetation is progressing with western wheatgrass and smooth brome. Weeds not observed, but need to be monitored and controlled during the active growing season.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of open grass field with western wheatgrass, smooth brome, and crested wheatgrass.