


**Inspection Photos**  
**Location Name: Hunt 8-60-17A**  
**Location ID: 457131**



**Photo 1 – Signs at Entrance**



**Photo 2 – Wellheads**



**Inspection Photos**  
**Location Name: Hunt 8-60-17A**  
**Location ID: 457131**



**Photo 3 – North Wellhead – Sign Missing**



**Photo 4 – North Wellhead – Sign Missing**






**Inspection Photos**  
**Location Name: Hunt 8-60-17A**  
**Location ID: 457131**



**Photo 5 – Separators**



**Photo 6 – West Separators missing Screen/Stack**



**Inspection Photos**  
**Location Name: Hunt 8-60-17A**  
**Location ID: 457131**



**Photo 7 – Compressors**



**Photo 8 – LACT**

**Inspection Photos**  
**Location Name: Hunt 8-60-17A**  
**Location ID: 457131**



**Photo 9 – Tank Battery**



**Photo 10 – Tank Battery**

