

**Inspection Photos**  
**Location Name: Hunt 8-60-17B**  
**Location ID: 457475**



**Photo 1 – Wellheads**



**Photo 2 – Far 2 East Wellheads missing Signs**



**Inspection Photos**  
**Location Name: Hunt 8-60-17B**  
**Location ID: 457475**



**Photo 3 – Gas Lift Injection Meter House**



**Photo 4 – Separators**





**Inspection Photos**  
**Location Name: Hunt 8-60-17B**  
**Location ID: 457475**



**Photo 5 – Separators**



**Photo 6 – Air Units and ECDs**

**Inspection Photos**  
**Location Name: Hunt 8-60-17B**  
**Location ID: 457475**



**Photo 7 – Tank Battery**



**Photo 8 – Tank Battery**

**Inspection Photos**  
**Location Name: Hunt 8-60-17B**  
**Location ID: 457475**



**Photo 9 – LACTS**



**Photo 10 – ECDs**



**Inspection Photos**  
**Location Name: Hunt 8-60-17B**  
**Location ID: 457475**



**Photo 11 – VRUs**



**Photo 12 – Electrical Equipment**

Inspection Photos  
Location Name: Hunt 8-60-17B  
Location ID: 457475



Photo 13 – Compressors



Photo 14 – Sign at Entrance

