



Photographic Log

Arapaho Unit Section 25S Tank

Battery

Excavation and Soil Sampling

(November 11th, 2021)



Photo No 1:

Description:
Arapaho Unit
Section 25S
excavation, facing
north.



Photo No 2:

Description:
Arapaho Unit
Section 25S
excavation, facing
east.



Photo No 3:

Description:
Arapaho Unit
Section 25S
excavation, facing
southeast.



Photo No 4:

Description:
Arapaho Unit
Section 25S
excavation, facing
northwest



Photo No 5:

Description:
Arapaho Unit
Section 25S
background
sampling borehole.
Samples were
collected at 4 and 6
foot depths.



Photo No 6:

Description:
Arapaho Unit
Section 25S
background
sampling borehole.
Samples were
collected at 4 and 6
foot depths.