

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #5599 from entrance to location.



Photo #5600 Storage tank not labeled.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #5601 Sight glass indicates the storage tank is full of an unknown fluid.



Photo #5603 No battery sign located at the tank battery.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #4867 from inspection #699803601 conducted on 9/13/21.