

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NWSE

Location ID: 324220



Photo #5621 from entrance to location.



Photo #5622 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NWSE

Location ID: 324220



Photo #5623 Storage unit not labeled.



Photo #5624 Sight glass indicates the storage tank is full of an unknown fluid.