

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/06/2022

Submitted Date:

01/09/2022

Document Number:

701004279

**FIELD INSPECTION FORM**
 Loc ID 304434 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 261479      | WELL | PR     | 08/01/2020  | GW         | 125-08410 | CURE 44-28443 | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good: ☒

|                      |                             |       |  |
|----------------------|-----------------------------|-------|--|
| <b>Signs/Marker:</b> |                             |       |  |
| Type                 | TANK LABELS/PLACARDS        |       |  |
| Comment:             | Metal sign by water tank    |       |  |
| Corrective Action:   |                             | Date: |  |
| Type                 | WELLHEAD                    |       |  |
| Comment:             | Lease sign mounted to fence |       |  |
| Corrective Action:   |                             | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                       |       |  |
| Type               | PUMP JACK                             |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |  |       |      |             |           |         |    |               |    |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 261479   | Type: | WELL | API Number: | 125-08410 | Status: | PR | Insp. Status: | PR |
| Producing Well       |  |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (Cure 33B-28443, 44-28443) 1900' W @ 39.67734/-102.18729 |       |      |             |           |         |    |               |    |
| Corrective Action:   |  |       |      |             |           |         |    | Date:         |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT