



99999999

WELL SITE INSPECTION FORM

Not on Computer

WELL NAME Hoffman-Lousberg 1 API NUMBER 05 - 123 - 7062
OPERATOR To/Heli/Dannelly PERMIT NUMBER 68-443
LOCATION SWNW 13-9N-57W COUNTY Weld
FIELD McKenzie INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) ☐ DATE 8/17/88 WELL STATUS: FN ☐ FD ☐ WO ☐

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED ☐ OPEN ☐ WELLHEAD SYSTEM INSTALLED _____TANK ID: YES ☐ NO ☐ NA ☐ WELL SIGN: YES ☐ NO ☐

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO ☐ YES ☐ TYPE _____METER RUN: YES ☐ NO ☐ WELL STATUS: PR ☐ TA ☐ SI ☐ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES ☒ NO ☐ PITS BACKFILLED: YES ☒ NO ☐MATERIAL BURIED: YES ☒ NO ☐ NA ☐ SITE CLEAN: YES ☒ NO ☐BOND RELEASE OK: YES ☒ NO ☐ FED ☐ HOLE MARKER: YES ☐ NO ☒

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS _____



00270718