

Inspection Photos  
Operator: Simcoe  
API: 067-09553  
Date: 1/7/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southwestern corner facing eastward. Vegetation largely snow covered. Observable vegetation includes: intermediate wheatgrass, smooth brome, and western wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the reference area comprised of open grass field, largely snow covered, with smooth brome and western wheatgrass observable.