

Inspection Photos  
Operator: Simcoe  
API: 067-06951  
Date: 1/7/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation largely snow covered. Observable vegetation includes: smooth brome, and western wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward. Inset shows dormant Canada thistles. Weeds need to be addressed during the active growing season.



Photo 4. View of the reference area comprised of open grass field, largely snow covered, with smooth brome and western wheatgrass observable.