

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /26SWSW

Location ID: 311558



Photo #5625 from entrance to location.



Photo #5626 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /26SWSW

Location ID: 311558



Photo #5627 Storage tank not labeled.



Photo #5628 Sight glass indicates the storage tank is full of an unknown fluid.