

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /26SESW

Location ID: 324192



Photo #5629 from entrance to location.



Photo #5630 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /26SESW

Location ID: 324192



Photo #5631 Storage tank not labeled.



Photo #5632 Sight glass indicates the storage tank is full of an unknown fluid.