

COLORADO O



99999999

ION COMMISSION

FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- <u>123 - 05618</u>		LEASE NAME: <u>Grabill 1</u>	
LOCATION: <u>NW SE 29-9N-56</u>		OPERATOR: <u>Utah Southern</u>	
DATE: <u>11-16-95</u>		INSPECTOR: <u>Ed Binkley (EBB)</u>	
Insp. Type: <u>SP</u>	Insp. Status: <u>PA</u>	PA: <input checked="" type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input checked="" type="radio"/> N

## INSPECTION ITEM

## COMMENTS

## INPUT

<b>Well ID Signs</b> (Rule 210)		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)	<u>Cultivated</u>	
<b>Miscellaneous</b>		

## CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00241908

NOV 21 1995

OIL &amp; GAS CONS. COM.