

Inspection Photos
Location Name: Pete Montoya B1
Location ID: 317803



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Pete Montoya B1
Location ID: 317803



Colorado Oil & Gas Conservation Commission
6670 Co Rd 21, Fort Lupton, CO 80621, USA
40.0965, -104.86642, 4925.5ft, 147°
01/12/2022 14:06:30



Colorado Oil & Gas Conservation Commission
6670 Co Rd 21, Fort Lupton, CO 80621, USA
40.09652, -104.86644, 4920.7ft, 148°
01/12/2022 14:06:43

Photo 3 TB sign

Photo 4 TB

Inspection Photos
Location Name: Pete Montoya B1
Location ID: 317803



Photo 5 Flow line manifold

Photo 6 Gas Meter Run

Inspection Photos
Location Name: Pete Montoya B1
Location ID: 317803



Photo 7 Horiz. Heated Sep.

Photo 8 card in meter house indicates that calibration is not current

Inspection Photos
Location Name: Pete Montoya B1
Location ID: 317803



Photo 9 Vertical Sep.

Photo 10 Stained soil has been removed from around Vert. Sep.