

Inspection Photos

ID: 150396

Operator: CHEMCO INC

Inspection Date: 1/12/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 1. Facing east toward the tank battery. Trucks are hauling out fluids from the tanks at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 2. There is oil stained soil from where trucks are loading out the fluids of the tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 3. There is water leaking out of the pipe shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 4. There is oil stained soils and evidence of water leaking out of the pipe shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 5. The berm around the tanks is not sufficient to contain a spill. The 3 ft. shovel was placed to show size of the berm which is approximately 12 inches at red line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 6. Facing northwest toward the tank battery. The berm around the tanks is not sufficient to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 6. There is E&P waste draining out of this tank overflow pipe.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 8. The sign at the battery is not properly installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 9. There is an active electric utility that is not secured and protected and is a safety concern. The box needs to be closed and secured and the electric line needs to be protected.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 10. There is various unused unnecessary equipment/supplies being stored at the location. The barrel shown at red arrow contains burnt ashes. Burning is prohibited on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022

Inspection Photos



Photo 11. Facing east at the location. There is various unused unnecessary equipment/supplies being stored at the location. All supplies not necessary for use on the location is prohibited.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 1/12/2022